



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
July 7


### Repair Work

Devil's Slide (post mile 39.14)

- Level 'A' (upper level ocean side) – cables that had been stressed once were checked for tension and re-stressed where necessary.
- Level 'B' (lower level ocean side) – Drilling for tie backs continued using two rigs. 43 of 58 tie backs now installed. Tie back stressing also continued.



Drilling at level B with reach over rig



Stressing tie backs – level B

- Level 'C' (lower level cliff side) – Tie back stressing continued.



Stressing tie backs – level C

- Level 'D' (upper level cliff side) – Drilling for tie backs continued today. 11 of 33 now installed.



Temporary Bench

Road Level

Drilling at level D – note the temporary bench used to support the drill rig at the required height

### Retaining (micropile) Wall

- Drilling and driving steel piles continued today. The 4 inch diameter steel piles are filled with cement slurry after being driven into the ground. 23 of 99 now installed.